

**Total Land Subsidence in the Butler Valley Area, La Paz County**  
**Based on Sentinel-1 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data**  
**Time Period of Analysis: 5.0 Years 04/23/2017 To 05/15/2022**

© ESA 2017 - 2022  
 © ASF 2017 - 2022


#### Explanation

04/23/2017 To 05/15/2022

Total Land Subsidence

Decorrelation/No Data
Greater 40 cm (15.7 in)
25 - 40 cm (9.8 - 15.7 in)
15 - 25 cm (5.9 - 9.8 in)
10 - 15 cm (3.9 - 5.9 in)
6 - 10 cm (2.4 - 3.9 in)
4 - 6 cm (1.6 - 2.4 in)
2 - 4 cm (0.8 - 1.6 in)
1 - 2 cm (0.4 - 0.8 in)
0 - 1 cm (0 - 0.4 in)

Subsidence Feature
Hardrock
Highways and Interstates
Interstate
US
State
Roads



1:100,000  
 0 0.5 1 2 3 4 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N  
 Projection: Transverse Mercator  
 Datum: North American 1983  
 Units: Meter  
 Created: 6/9/2022

